

QUALITY PEOPLE. QUALITY SERVICE.

KIT MASTERS

SPECIALIZING IN:



- FAN CLUTCHES
- REBUILD KITS
- ACCESSORIES



KIT MASTERS
FAN CLUTCH EXPERTS

Kit Masters, Inc. manufactures heavy-duty aftermarket components, specializing in remanufactured fan clutches, rebuild kits and accessories. Kit Masters was founded in 1996, in the garage, by the father and son team of Keith and Darrin Swanson.

KIT MASTERS
FAN CLUTCH EXPERTS



KIT MASTERS

FAN CLUTCHES, REBUILD KITS AND ACCESSORIES!

PART #	TYPE	DESCRIPTION	APPLICATION FIT
14-256	GoldTop Fan Clutch Rebuild Kit	Features a 2.56" fan pilot and two pulley bearings	995530, 994985, 994900, 995568, 995575, 995534, 994347, 995567, Q995568, 14256, Q995575
14-256-1	GoldTop Fan Clutch Rebuild Kit	The 14-256-1 features a 2.56" fan pilot and one pulley bearing	994902, 14256-1, 995031, 994353, 995669, 142561, 14-256-1, Q995669,
24-256	2-Speed GoldTop Rebuild Kit	Auto Lock feature prevents on-the-road failures	995509, 995510, 995518, 995519, 995557, 995582, 995617, 995623, 995624, Gold Top, 24256, 24-256
24-256-1	2-Speed GoldTop Rebuild Kit	Auto Lock feature prevents on-the-road failures	995511, 995527, 995559, 995622
8801N	Kysor-Style Fan Clutch	It can be used to replace K22, K26, K30 and K32 rear air fan clutches	8801x, 8801X, 10900995001, 1090-09950-01, 10900850001, 1090-08500-01, 10900950001, 1090-09500-01, 10900960001, 1090-09600-01, 10900965001, 1090-09650-01, 10900965001B, 1090-09650-01B, 10900975001, 1090-09750-01, 10900975001B, 1090-09750-01B, 10900995001B, 1090-09950-01B, 10900960001B
7500HP	7.5-Inch Fan Clutch Rebuild Kit	Easy choice for rebuilding Horton® HT/S®-style fan clutches	994307, 994324
9500HP	9.5-Inch Fan Clutch Rebuild Kit	Easy choice for rebuilding Horton® HT/S®-style fan clutches	994305, 994322, 994388, 994336, 601158, 994389, 894305
8500SKL	RA Kysor-Style Seal & Lining Kit (K-22)	Seal and lining kit for rebuilding rear air K-22 Kysor-style fan clutches	10330543503, 1033-05435-03, 9908400, 1695794C1
8800SKL	RA Kysor-Style Seal & Lining Kit (K-26 thru K-32)	Seal and lining kit for rebuilding rear air K-26, K-30 & K-32 Kysor-style fan clutches	10330933901, 1033-09339-01, 9908405, 85112571, 2509688C91, 10334060002, 1033-40600-02, 85134490
8581-01	Kysor-Style Hub Bearing Kit	Pulley bearing kit for rebuilding Kysor-style fan clutch hubs (pulley & bracket). Includes one 6209 bearing and one 6207 bearing. This is the most popular bearing kit for rear-air hubs	10330778101, 1033-07781-01, 9908300, 1695793C91
8582-01	Kysor-Style Hub Bearing Kit	Pulley bearing kit for rebuilding Kysor-style fan clutch hubs (pulley & bracket). Includes one 5207 bearing	858201, 8582-01, 10330778201, 1033-07782-01, 9908301, 1696090C91
4205	S & HTS Series Seal Kit	Seal kit for S & HT/S style air-engaged fan clutches	994205, 994370, 6L6346, 6L-6-346
3282	3-way Solenoid Valve NO-NC 125NPTF, 12VDC		993282, 993286, 983299, 993240, 983226, 983238, 993312, 993287, 993284, 993248, 993232, 993249, 993314, 993356, 208223415, 20822-3415, 983431, C4H780DC14L9
91014	Caterpillar Fan Clutch	Horton® HT/S®-style fan clutches. Rebuild with kit #: 9500HP	591014, 791014, 981064, 981110, 981148, 981349, 981362, 981363, 991076, 991119, 991152, 991356, 991372, 991373, 791014RMAN
91024	Detroit Diesel Fan Clutch	Horton® HT/S®-style fan clutches. Rebuild with kit #: 9500HP	981050, 591024, 981104, 981120, 981143, 981146, 981147, 981176, 981224, 981324, 991064, 991113, 991127, 991149, 991324, 791065, 981342, 991349, 91065, 981061
91027	Caterpillar Fan Clutch	Horton® HT/S®-style fan clutches. Rebuild with kit #: 9500HP	591027, 791027, 819875, 981001, 981053, 981054, 981126, 991012, 991017, 991067, 991068, 991132, 0511369035, 05-11369-035, 0511369036, 05-11369-036, 0511369041, 05-11369-041, 791125, 791125RMAN
99103	Caterpillar Fan Clutch	2-speed equivalent: 99103-2. Rebuild with kit number 14-256	989103, 999103, 99a9103, 79a9103, 0525159014, 05-25159-014, 799103
99142	Mercedes Fan Clutch	2-speed equivalent: 99142-2. Rebuild with kit #: 14-256-1	989142, 999142, 799142
99188	Cummins Fan Clutch	2-speed equivalent: 99188-2. Rebuild with kit #: 14-256 & 150SK	989188, 999188, 799188, 79a9515, 999515, 989515, 99a9515, 98a9515, HOR99A9515
99223	Detroit Diesel Fan Clutch	2-speed equivalent: 99223-2. Rebuild with kit #: 14-256	989223, 999223, 799223, 79a9223, 99a9223, 98a9223
99334	Caterpillar Fan Clutch	2-speed equivalent: 99334-2. Rebuild with kit #: 14-256	989334, 999334, f176013317, f17-6013-317, f171000317, f17-1000-317, 79a9334, 99a9334, M6X3050, 799334, 98a9334
99346	Caterpillar Fan Clutch	2-speed equivalent: 99346-2. Rebuild with kit #: 14-256	989346, 999346, f171000320, f17-1000-320, 99a9346, 79a9346, 799346, 799437, 79a9437, 989437, 999437, 99a9437, f171000337, f17-1000-337, 98a9346, 98a9437
99495	Mack Fan Clutch	2-speed equivalent: 99495-2. Rebuild with kit #: 14-256	989474, 999474, 999495, 989495, 65140602, 6514-060-2, 40MH441M, 85123190, 799495, 999348, 989348, 65140602, 40MH415AM, 40MH415M
99782-2	2-Speed Cummins Fan Clutch	Rebuild with kit #: 24-256	79A8202, 79A9782, 98A9782, 99A9782, F176017M03, F17-6017M03, 995862, 99586-2
99809	Caterpillar Fan Clutch	2-speed equivalent: 99809-2. Rebuild with kit #: 14-256	989809, 999809, f171000329, f17-1000-329, 79a9809, 99a9809, M6X0886, 799809, F176013329, F17-6013-329
99897	Cummins Fan Clutch	2-speed equivalent: 99897-2. Rebuild with kit #: 14-256	999831, 999890, 999897, 989897, f1760055012, f17-6005-5012, f1760055122, f17-6005-5122, 989890, 989831, f1710035112, f17-1003-5112, 99a9897, 79a9897, f1760115120, f17-6011-5120, f1760115122, f17-6011-5122, 989848, 999848, 98a9897
638667	PolyForce™ Belt Tensioner	Instant upgrade from the Gates 38667, the most popular belt tensioner on '08-'17 Freightliners with DD13, DD15 & DD16 engines	GT38667, 38667, A4722000170, A4-72200-0170, 49603, 89498, EA4722000270, EA4-72200-0270, EA4722000170, EA4-72200-0170, A4722000270, A4-72200-0270, A4722000470